






Section GB51 GB5 4,300 mN ш GB1**286**B**RL** GB1 / GB2 GB13 GB2 GB14 GB25 GB31 GB25 GB31 GB46 280 RL GB22 GB-18-04 GB28 - 25 260 RL - 25 HP m - 25 m GB-18-06 GB-18-03 25 m **GB48** 240 RL 567 25 m 50 m 220 RL 75 50 m50 - 75 75 75 N + 0 0 75 200 RL -lod L Section - 75 - 75 100 m thick 100 4 M900 0 00 0 N 180 RL 180 RL 100 100 100 08500 125 - 100 m 160 RL - 160 RL 100 m 140 RL 2324400 V 125 m 125 140 RL 2324300 562800 150 125







What does this all mean?

SLIDE 9: Big hole in the drilling.

SLIDE 10: Lot's of holes in the drilling. Looks like there may be 2 zones. Plunge is very shallow.

SLIDE 11: SLIDE 5 shows section 4,200 N with a 100 m thick slice (50 m on either side of the deposit). SLIDE 7 is the same section, this time with a 25 m section (12.5 m on either side). Notice that most of the holes on the section that did not intersect thick mineralization were drilled either too shallow and crossed above the Great Burnt zone or they were too deep and crossed under the zone.

SLIDE 12: The deeper holes probably aren't where we thick they are based on the fact that the original drillholes were very thin in diameter and that the hole deviation (change in dip and azimuth) is so severe. This whole section should be re-drilled using NQ-sized core.

For example, holes GB85 and GB86 were collared with a dip of -85 and both holes shallowed as much as -36 and -35 (50 degree change in dip). Yet the azimuths changed only 4-5 degrees. This is very unlikely. These holes probably never even crossed the plane of mineralization, rotating instead off section.

